	pe Hi		DBs	Time Stamp Commen	its Error Defini Errors
BRS	S 2	multi near1 chip near1 module and vital near1 product near1 data	USPAT; US-PGPU	TB 2003/08/08 12:54	0
BRS	S 1	"5414715".PN.	USPAT	2003/08/07 14:06	0
BRS	S 1	"5390351".PN.	USPAT	2003/08/07 14:06	0
BR	S 1	"5369604".PN.	USPAT	2003/08/07 14:06	
BRS	S 1	"5325368".PN.	USPAT	2003/08/07 14:07	0
BRS	S 1	"4710931".PN.	USPAT	2003/08/07 14:07	0
BRS	S 1	"4025906".PN.	USPAT	2003/08/07 14:08	0
BRS	S 1	"4604744".PN.	USPAT	2003/08/07 14:09	0
BRS	S 1	"4606024".PN.	USPAT	2003/08/07 14:10	0
0 BRS	S 1	"4710931".PN.	USPAT	2003/08/07 14:10	0
1 BRS	S 1	"5056093".PN.	USPAT	2003/08/07 14:10	0
2 BRS	S 1	"5325368".PN.	USPAT	2003/08/07 14:11	0
3 BR	S 1	"5390351".PN.	USPAT	2003/08/07 14:11	0
4 IS&	≿R I	("5929646").PN.	USPAT; US-PGPU	Љ 2003/08/08 12:59	0
5 BRS	S 1	"5701085".PN.	USPAT	2003/08/08 12:56	0
6 BR	S 1	"5635846".PN.	USPAT	2003/08/08 12:56	0
7 BR	S 1	"5408190".PN.	USPAT	2003/08/08 12:57	0
8 BR	S 1	"5207585".PN.	USPAT	2003/08/08 12:57	0
9 BR	S 1	"5207585".PN.	USPAT	2003/08/08 12:57	0
0 BR	S 1	"4954878".PN.	USPAT	2003/08/08 12:57	0
1 BRS	S 1	"4954878".PN.	USPAT	2003/08/08 12:58	0
2 BR	S I	"4862076".PN.	USPAT	2003/08/08 12:58	0
3 BR	S 1	"4954878".PN.	USPAT	2003/08/08 12:58	0
4 BR	S 1	"3982320".PN.	USPAT	2003/08/08 12:58	0
5 BR	S 9835	IC and insert\$3 and count\$3 and	USPAT; US-PGPU	ЛВ 2003/08/08 13:00	0

Ċ.	,		detect\$3			
26	BRS	1461	(IC and insert\$3 and count\$3 and detect\$3) and tracking	USPAT; US-PGPUB	2003/08/08 13:00	0
7	BRS	1	((IC and insert\$3 and count\$3 and detect\$3) and tracking) and receptacle and planar and interposer	USPAT; US-PGPUB	2003/08/08 13:02	0
8	BRS	1	((IC and insert\$3 and count\$3 and detect\$3) and tracking) and receptacle and interposer	USPAT; US-PGPUB	2003/08/08 13:02	0
29	BRS	1	((IC and insert\$3 and count\$3 and detect\$3) and tracking) and interposer	USPAT; US-PGPUB	2003/08/08 13:03	0
50	BRS	12	((IC and insert\$3 and count\$3 and detect\$3) and tracking) and mcm	USPAT; US-PGPUB	2003/08/08 13:39	0
51	BRS	19	ic and insert\$3 near1 count	USPAT; US-PGPUB	2003/08/08 13:48	0
12	BRS	0	ic and detect\$3 and parity and hotswap	USPAT; US-PGPUB	2003/08/08 13:49	0
33	BRS	152	ic and detect\$3 and parity and backplane	USPAT; US-PGPUB	2003/08/08 13:49	0
34	BRS	114	(ic and detect\$3 and parity and backplane) and count and insert\$3	USPAT; US-PGPUB	2003/08/08 13:49	0
35	BRS	0	((ic and detect\$3 and parity and backplane) and count and insert\$3) and interposer	USPAT; US-PGPUB	2003/08/08 13:49	0
36	BRS	2	((ic and detect\$3 and parity and backplane) and count and insert\$3) and planar	USPAT; US-PGPUB	2003/08/08 13:59	0
37	BRS	2241	smart near1 card and insert\$3 and count\$3	USPAT; US-PGPUB	2003/08/08 14:00	0
38	BRS	0	(smart near1 card and insert\$3 and count\$3) and receptacle and interposer and count	USPAT; US-PGPUB	2003/08/08 14:00	0
39	BRS	138	(smart near1 card and insert\$3 and count\$3) and receptacle and count	USPAT; US-PGPUB		0
10	BRS	83	((smart near1 card and insert\$3 and count\$3) and receptacle and count) and detect\$3 and track\$3	USPAT; US-PGPUB		0
11	BRS	33	(((smart near l card and insert\$3 and count\$3) and receptacle and count) and detect\$3 and track\$3) and planar	USPAT; US-PGPUB	2003/08/10 10:37	0
12	BRS	1	"5556958".PN.	USPAT	2003/08/10 10:26	0
		1	"5495240".PN.	USPAT	2003/08/10 10:26	0
	BRS	1	"5327121".PN.	USPAT	2003/08/10 10:26	0
		1	"5226137".PN.	USPAT	2003/08/10 10:26	0
		1	"5177742".PN.	USPAT	2003/08/10 10:27	0
		1	"5111058".PN.	USPAT	2003/08/10 10:27	0
		1	"5051897".PN.	USPAT	2003/08/10 10:27	0
19	BRS	1	"5038299".PN.	USPAT	2003/08/10 10:27	0

50 BRS	5 1	"5631883".PN.	USPAT	2003/08/10 10:28	0
51 BRS	S 1	"5627361".PN.	USPAT	2003/08/10 10:28	0
52 BRS	S 1	"5241161".PN.	USPAT	2003/08/10 10:29	0
53 BRS	s 1	"4943708".PN.	USPAT	2003/08/10 10:29	0
54 BRS	S 1	"4965727".PN.	USPAT	2003/08/10 10:29	0
55 BRS	3 1	"4965727" PN.	USPAT	2003/08/10 10:30	0
					\
56 BRS	5 1	"4764666".PN.	USPAT	2003/08/10 10:30	0
57 BRS	3678	ic and identify\$3 and track\$3 and count\$3	USPAT; US-PGPUB	2003/08/10 10:37	0
58 BRS	S 0	(ic and identify\$3 and track\$3 and count\$3) and insert43	USPAT; US-PGPUB	2003/08/10 10:38	0
59 BRS	S 226	(ic and identify\$3 and track\$3 and count\$3) and receptacle	USPAT; US-PGPUB	2003/08/10 10:38	0
60 BRS	S 1	(((ic and identify\$3 and track\$3 and count\$3) and receptacle) and planar)	USPAT; US-PGPUB	2003/08/10 10:39	0
61 BRS	\$ 54	and mcm ((ic and identify\$3 and track\$3 and count\$3) and receptacle) and planar	USPAT; US-PGPUB	2003/08/10 10:39	0
62 IS&	R 1	("6142809").PN.	USPAT; US-PGPUB	2003/08/10 11:36	0
63 BRS	3 1	"5816828".PN.	USPAT	2003/08/10 11:09	0
64 BRS	S 1	"5791915".PN.	USPAT	2003/08/10 11:09	0
65 BRS	S 1	"5100332".PN.	USPAT	2003/08/10 11:10	0
66 BRS	S 1	"5139437".PN.	USPAT	2003/08/10 11:10	0
67 BRS	S 1	"5186642".PN.	USPAT	2003/08/10 11:10	0
68 BRS		"5460538".PN.		2003/08/10 11:11	
			USPAT		0
69 BRS	3 1	"5791915".PN.	USPAT	2003/08/10 11:11	0
70 BRS	5 1	"5816828".PN.	USPAT	2003/08/10 11:11	0
71 IS&	R 5	(("5506611") or ("6547363") or ("5365312") or ("6267619") or ("5334827")).PN.	USPAT; US-PGPUB	2003/08/10 11:47	o
72 IS&	R 1	("6431453").PN.	USPAT; US-PGPUB	2003/08/10 11:46	0
73 IS&	R 1	("5494544").PN.	USPAT; US-PGPUB	2003/08/10 11:46	0
74 BRS	S 937	insertion with count	USPAT; US-PGPUB	2003/08/10 11:47	o

]	BRS	183	(insertion with count) and (ic or	USPAT; US-PGPUB	2003/08/10 12:02	0
			"integrated circuit")		!	į
Ī	BRS	1	"4361945".PN.	USPAT	2003/08/10 11:51	0
I	BRS	1	"5089970".PN.	USPAT	2003/08/10 11:51	0
I	BRS	1	"5311438".PN.	USPAT	2003/08/10 11:52	0
I	BRS	1	"5396703".PN.	USPAT	2003/08/10 11:52	0
I	BRS	1	"5910894".PN.	USPAT	2003/08/10 11:52	0
I	BRS	1	"6202981".PN.	USPAT	2003/08/10 11:52	0
İ	BRS	5476	detect\$3 and ic with card	USPAT; US-PGPUB	2003/08/10 12:03	0
I	BRS	295	(detect\$3 and ic with card) and insertion and track\$3	USPAT; US-PGPUB	2003/08/10 12:05	0
I	BRS	186	((detect\$3 and ic with card) and insertion and track\$3) and count\$3	USPAT; US-PGPUB	2003/08/10 12:05	0
I	BRS	1	(((detect\$3 and ic with card) and insertion and track\$3) and count\$3) and receptacle and planar	USPAT; US-PGPUB	2003/08/10 12:04	o
i	BRS	2258	(detect\$3 and ic with card) and insertion and track\$3	USPAT; US-PGPUB	2003/08/10 12:05	0
I	BRS	1826	(detect\$3 and ic with card) and inser tion and track\$3	USPAT	2003/08/10 12:06	0
I	BRS	0	((detect\$3 and ic with card) and inser tion and track\$3) and ((((detect\$3 and ic with card) and insertion and	USPAT	2003/08/10 12:06	0
I	BRS	8	((detect\$3 and ic with card) and insertion and track\$3) and (((detect\$3 and ic with card) and insertion and	USPAT	2003/08/10 15:33	0
)	IS&R	1	("6330977").PN.	USPAT; US-PGPUB	2003/08/10 15:33	0
I	BRS	1	(("6330977").PN.) and count\$3	USPAT; US-PGPUB	2003/08/10 15:34	0
i	BRS	1	((("6330977").PN.) and count\$3) and ic	USPAT; US-PGPUB	2003/08/10 15:35	0
I	BRS	1	(((("6330977").PN.) and count\$3) and ic) and insert\$3	USPAT; US-PGPUB	2003/08/10 16:12	o
F	BRS	0	(("6330977").PN.) and mcm	USPAT; US-PGPUB	2003/08/11 07:33	0

	Type	L#	Hits		DBs Time Stam Comn	ne Error Definition E
1	IS&R	Ll	1	("6330977").PN.	USPA 2003/08/11 T; 07:33 US-P	0
2	BRS	L2	1	l and planar	USPA 2003/08/11 T; 08:05 US-P	0
3	BRS	L3	0	1 and interposer	USPA 2003/08/11 T; 08:16 US-P	0
ı	BRS	L4	56	vital with product and ic	USPA 2003/08/11 T; 08:16 US-P	0
5	BRS	L5	38	4 and insert\$3	USPA 2003/08/11 T; 08:18 US-P	0
\$	BRS	L6	Ō	5 and cout\$3	USPA 2003/08/11 T; 08:18 US-P	0
7	BRS	L7	29	5 and count\$3	USPA 2003/08/11 T; 08:22 US-P	0
3	BRS		0	7 and planar and pcb	USPA 2003/08/11 T; 08:23 US-P	0
)	BRS	L9	0	7 and pcb	USPA 2003/08/11 T; 08:23 US-P	0
10	BRS	L10	1	7 and interposer	USPA 2003/08/11 T; 08:23 US-P	0